



# Smothers ES Lead Water Test Results



## FY18 Filter Test

### Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001600	5/16/2017	5/16/2018	3	Cooler	In hallway adjacent to room 310	WF-52017-001600	11/17/2017	FT-FY18--52017-001600-A	<1	FT-FY18--52017-001600-B	<1
WS- 001601	5/16/2017	5/16/2018	3	Break Room	In break room	WF-52017-001601	11/17/2017	FT-FY18--52017-001601-A	<1	FT-FY18--52017-001601-B	<1
WS- 001603	11/9/2017	11/9/2018	2	Health Suite	In health suite in restroom	WF-112017-001603	11/17/2017	FT-FY18-112017-001603-A	<1	FT-FY18-112017-001603-B	<1
WS- 001610	11/9/2017	11/9/2018	1	Bathroom	In classroom 102 in bathroom	WF-112017-001610	11/17/2017	FT-FY18-112017-001610-A	<1	FT-FY18-112017-001610-B	<1
WS- 001616	11/9/2017	11/9/2018	1	Bathroom	In classroom 113 in bathroom	WF-112017-001616	11/17/2017	FT-FY18-112017-001616-A	<1	FT-FY18-112017-001616-B	<1

## Food Prep Sink

### Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001609	1	Food Prep Sink	In kitchen third clockwise from entry door	11/17/2017	FT-FY18-102017-001609-A	<1	FT-FY18-102017-001609-B	<1