



# Smothers ES Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-001600	3/29/2018	3/29/2019	3	Cooler	In hallway adjacent to room 310	WF-03292018-001600	11/21/2018	FT-FY19-112018-001600-A	< 1	FT-FY19-112018-001600-B	< 1
WS-001601	3/29/2018	3/29/2019	3	Break Room	In break room	WF-03292018-001601	11/21/2018	FT-FY19-112018-001601-A	< 1	FT-FY19-112018-001601-B	< 1
WS-001602	3/29/2018	3/29/2019	3	Cooler	In hallway adjacent to room 301	WF-03292018-001602	11/21/2018	FT-FY19-112018-001602-A	< 1	FT-FY19-112018-001602-B	< 1
WS-001603	10/15/2018	10/15/2019	2	Health Suite	In health suite in restroom	WF-10152018-001603	11/21/2018	FT-FY19-112018-001603-A	< 1	FT-FY19-112018-001603-B	< 1
WS-001604	3/29/2018	3/29/2019	2	Cooler	In hallway adjacent to room 201	WF-03292018-001604	11/21/2018	FT-FY19-112018-001604-A	< 1	FT-FY19-112018-001604-B	< 1
WS-001605	3/29/2018	3/29/2019	2	Cooler	In hallway adjacent to room 212	WF-03292018-001605	11/21/2018	FT-FY19-112018-001605-A	< 1	FT-FY19-112018-001605-B	< 1
WS-001606	3/29/2018	3/29/2019	1	Cooler	In hallway adjacent to room 108	WF-03292018-001606	11/21/2018	FT-FY19-112018-001606-A	< 1	FT-FY19-112018-001606-B	< 1
WS-001610	10/15/2018	10/15/2019	1	Bathroom	In classroom 102 in bathroom	WF-10152018-001610	11/21/2018	FT-FY19-112018-001610-A	< 1	FT-FY19-112018-001610-B	< 1
WS-001611	10/15/2018	10/15/2019	1	Bathroom	In classroom 104 in bathroom	WF-10152018-001611	11/21/2018	FT-FY19-112018-001611-A	< 1	FT-FY19-112018-001611-B	< 1
WS-001612	10/15/2018	10/15/2019	1	Bathroom	In classroom 108 in bathroom	WF-10152018-001612	11/21/2018	FT-FY19-112018-001612-A	< 1	FT-FY19-112018-001612-B	< 1
WS-001613	3/29/2018	3/29/2019	1	Cooler	In hallway adjacent to room 104	WF-03292018-001613	11/21/2018	FT-FY19-112018-001613-A	< 1	FT-FY19-112018-001613-B	< 1
WS-001614	10/15/2018	10/15/2019	1	Bathroom	In classroom 110 in bathroom	WF-10152018-001614	11/21/2018	FT-FY19-112018-001614-A	< 1	FT-FY19-112018-001614-B	< 1
WS-001615	10/15/2018	10/15/2019	1	Bathroom	In classroom 111 in bathroom	WF-10152018-001615	11/21/2018	FT-FY19-112018-001615-A	< 1	FT-FY19-112018-001615-B	< 1
WS-001616	10/15/2018	10/15/2019	1	Bathroom	In classroom 113 in bathroom	WF-10152018-001616	11/21/2018	FT-FY19-112018-001616-A	< 1	FT-FY19-112018-001616-B	< 1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-001609	1	Food Prep Sink	In kitchen third clockwise from entry door	11/21/2018	FT-FY19-112018-001609-A	< 1	FT-FY19-112018-001609-B	< 1