



Sousa MS Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009644	4/29/2019	4/29/2020	1	Cooler	In hallway adjacent to room B122	High Right	WF-04292019-009644	1/9/2020	FT-FY20-122019-009644-A	<1	FT-FY20-122019-009644-B	<1
WS- 009645	4/29/2019	4/29/2020	1	Cooler	In hallway adjacent to room B122	Low Left	WF-04292019-009645	1/9/2020	FT-FY20-122019-009645-A	<1	FT-FY20-122019-009645-B	<1
WS- 009646	4/29/2019	4/29/2020	1	Health Suite	In health suite B122		WF-04292019-009646	1/9/2020	FT-FY20-122019-009646-A	<1	FT-FY20-122019-009646-B	<1
WS- 010987	4/29/2019	4/29/2020	1	Break Room	In mailroom B130		WF-04292019-010987	1/9/2020	FT-FY20-122019-010987-A	<1	FT-FY20-122019-010987-B	<1
WS- 010988	4/29/2019	4/29/2020	1	Health Suite	In health suite B122 in restroom		WF-04292019-010988	1/9/2020	FT-FY20-122019-010988-A	<1	FT-FY20-122019-010988-B	<1
WS- 011019	4/29/2019	4/29/2020	1	Cooler	In hallway across from backstage D101	Low Left	WF-04292019-011019	1/9/2020	FT-FY20-122019-011019-A	<1	FT-FY20-122019-011019-B	<1
WS- 011020	4/29/2019	4/29/2020	1	Cooler	In hallway across from backstage D101	High Right	WF-04292019-011020	1/9/2020	FT-FY20-122019-011020-A	<1	FT-FY20-122019-011020-B	<1
WS- 011021	4/29/2019	4/29/2020	1	Cooler	In boys' locker room D107	Low Left	WF-04292019-011021	1/9/2020	FT-FY20-122019-011021-A	<1	FT-FY20-122019-011021-B	<1
WS- 011022	4/29/2019	4/29/2020	1	Cooler	In boys' locker room D107	High Right	WF-04292019-011022	1/9/2020	FT-FY20-122019-011022-A	<1	FT-FY20-122019-011022-B	<1
WS- 011023	4/29/2019	4/29/2020	1	Cooler	In girls' locker room D119	Low Left	WF-04292019-011023	1/9/2020	FT-FY20-122019-011023-A	<1	FT-FY20-122019-011023-B	<1
WS- 011024	4/29/2019	4/29/2020	1	Cooler	In girls' locker room D119	High Right	WF-04292019-011024	1/9/2020	FT-FY20-122019-011024-A	<1	FT-FY20-122019-011024-B	<1
WS- 011025	4/29/2019	4/29/2020	Basement	Ice Maker	In kitchen (ice maker)		WF-04292019-011025	1/9/2020	FT-FY20-122019-011025-A	<1	FT-FY20-122019-011025-B	<1
WS- 011031	4/29/2019	4/29/2020	2	Cooler	In hallway adjacent to room C201	High Left	WF-04292019-011031	1/9/2020	FT-FY20-122019-011031-A	<1	FT-FY20-122019-011031-B	<1
WS- 011032	4/29/2019	4/29/2020	2	Cooler	In hallway adjacent to room C201	High Right	WF-04292019-011032	1/9/2020	FT-FY20-122019-011032-A	<1	FT-FY20-122019-011032-B	<1
WS- 011062	4/29/2019	4/29/2020	2	Cooler	In hallway adjacent to room A202	High Right	WF-04292019-011062	1/9/2020	FT-FY20-122019-011062-A	<1	FT-FY20-122019-011062-B	<1
WS- 011063	4/29/2019	4/29/2020	2	Cooler	In hallway adjacent to room A202	Low Left	WF-04292019-011063	1/9/2020	FT-FY20-122019-011063-A	<1	FT-FY20-122019-011063-B	<1
WS- 011068	4/29/2019	4/29/2020	3	Break Room	In staff lounge B314		WF-04292019-011068	1/9/2020	FT-FY20-122019-011068-A	<1	FT-FY20-122019-011068-B	<1
WS- 011069	4/29/2019	4/29/2020	3	Cooler	In hallway adjacent to room A302	Low Left	WF-04292019-011069	1/9/2020	FT-FY20-122019-011069-A	<1	FT-FY20-122019-011069-B	<1
WS- 011070	4/29/2019	4/29/2020	3	Cooler	In hallway adjacent to room A302	High Right	WF-04292019-011070	1/9/2020	FT-FY20-122019-011070-A	<1	FT-FY20-122019-011070-B	<1
WS- 011085	4/29/2019	4/29/2020	3	Cooler	In hallway adjacent to room C301		WF-04292019-011085	1/9/2020	FT-FY20-122019-011085-A	<1	FT-FY20-122019-011085-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011027	7/1/2019	7/1/2020	Basement	Food Prep Sink	In kitchen on north wall	Left	WF-07012019-011027	1/9/2020	FT-FY20-122019-011027-A	<1	FT-FY20-122019-011027-B	<1