



Sousa Middle School Lead in Water Test Results

FY24 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009642	5/1/2023	5/1/2024	1	Cooler	In hallway adjacent to room A102	Low Left	WF-05012023-009642	10/25/2023	FT-FY24-09282023-009642-A	<1	FT-FY24-09282023-009642-B	<1
WS- 009643	5/1/2023	5/1/2024	1	Cooler	In hallway adjacent to room A102	High Right	WF-05012023-009643	10/25/2023	FT-FY24-09282023-009643-A	<1	FT-FY24-09282023-009643-B	<1
WS- 009644	5/1/2023	5/1/2024	1	Cooler	In hallway adjacent to room B122	High Right	WF-05012023-009644	10/25/2023	FT-FY24-09282023-009644-A	<1	FT-FY24-09282023-009644-B	<1
WS- 009645	5/1/2023	5/1/2024	1	Cooler	In hallway adjacent to room B122	Low Left	WF-05012023-009645	10/25/2023	FT-FY24-09282023-009645-A	<1	FT-FY24-09282023-009645-B	<1
WS- 009646	5/1/2023	5/1/2024	1	Health Suite	In health suite B122		WF-05012023-009646	10/25/2023	FT-FY24-09282023-009646-A	<1	FT-FY24-09282023-009646-B	<1
WS- 010988	5/1/2023	5/1/2024	1	Health Suite	In health suite B122 in restroom		WF-05012023-010988	10/25/2023	FT-FY24-09282023-010988-A	<1	FT-FY24-09282023-010988-B	<1
WS- 011015	5/1/2023	5/1/2024	1	Cooler	In hallway adjacent to room C101	Low Left	WF-05012023-011015	10/25/2023	FT-FY24-09282023-011015-A	<1	FT-FY24-09282023-011015-B	<1
WS- 011016	5/1/2023	5/1/2024	1	Cooler	In hallway adjacent to room C101	High Right	WF-05012023-011016	10/25/2023	FT-FY24-09282023-011016-A	<1	FT-FY24-09282023-011016-B	<1
WS- 011017	5/1/2023	5/1/2024	1	Cooler	In hallway adjacent to gym D111	Low Left	WF-05012023-011017	10/25/2023	FT-FY24-09282023-011017-A	<1	FT-FY24-09282023-011017-B	<1
WS- 011019	5/1/2023	5/1/2024	1	Cooler	In hallway across from backstage D101	Low Left	WF-05012023-011019	10/25/2023	FT-FY24-09282023-011019-A	<1	FT-FY24-09282023-011019-B	<1
WS- 011020	5/1/2023	5/1/2024	1	Cooler	In hallway across from backstage D101	High Right	WF-05012023-011020	10/25/2023	FT-FY24-09282023-011020-A	<1	FT-FY24-09282023-011020-B	<1
WS- 011025	5/1/2023	5/1/2024	Basement	Ice Maker	In kitchen (ice maker)		WF-05012023-011025	10/25/2023	FT-FY24-09282023-011025-A	<1	FT-FY24-09282023-011025-B	<1
WS- 011031	5/1/2023	5/1/2024	2	Cooler	In hallway adjacent to room C201	High Left	WF-05012023-011031	10/25/2023	FT-FY24-09282023-011031-A	<1	FT-FY24-09282023-011031-B	<1
WS- 011032	5/1/2023	5/1/2024	2	Cooler	In hallway adjacent to room C201	High Right	WF-05012023-011032	10/25/2023	FT-FY24-09282023-011032-A	<1	FT-FY24-09282023-011032-B	<1
WS- 011062	5/1/2023	5/1/2024	2	Cooler	In hallway adjacent to room A202	High Right	WF-05012023-011062	10/25/2023	FT-FY24-09282023-011062-A	<1	FT-FY24-09282023-011062-B	<1
WS- 011063	5/1/2023	5/1/2024	2	Cooler	In hallway adjacent to room A202	Low Left	WF-05012023-011063	10/25/2023	FT-FY24-09282023-011063-A	<1	FT-FY24-09282023-011063-B	<1
WS- 011068	5/1/2023	5/1/2024	3	Break Room	In staff lounge B314		WF-05012023-011068	10/25/2023	FT-FY24-09282023-011068-A	<1	FT-FY24-09282023-011068-B	<1
WS- 011069	5/1/2023	5/1/2024	3	Cooler	In hallway adjacent to room A302	Low Left	WF-05012023-011069	10/25/2023	FT-FY24-09282023-011069-A	<1	FT-FY24-09282023-011069-B	<1
WS- 011085	5/1/2023	5/1/2024	3	Cooler	In hallway adjacent to room C301		WF-05012023-011085	10/25/2023	FT-FY24-09282023-011085-A	<1	FT-FY24-09282023-011085-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011027	1/23/2023	1/23/2024	Basement	Food Prep Sink	In kitchen on north wall	Left	WF-01232023-011027	10/25/2023	FT-FY24-09282023-011027-A	<1	FT-FY24-09282023-011027-B	<1

FY24 Filter Test

Greater than 5ppb - Devices requiring remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010987	5/1/2023	5/1/2024	1	Break Room	In mailroom B130		WF-05012023-010987	10/25/2023	FT-FY24-09282023-010987-A	<1	FT-FY24-09282023-010987-B	16.6