



STEAD REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 STEAD RECREATION CENTER	5/28/2016	WS- 006531	Fountain	Ground Floor	Exterior adjacent restroom Right High	WT-042916-6548- A	< 1	WT-042916-6548- B	< 1				
2 STEAD RECREATION CENTER	5/28/2016	WS- 006532	Fountain	Ground Floor	Exterior adjacent to restroom Left Low	WT-042916-6549- A	< 1	WT-042916-6549- B	< 1				
3 STEAD RECREATION CENTER	5/28/2016	WS- 006533	Fountain	Ground Floor	Exterior adjacent to back play ground Right High	WT-042916-6550- A	< 1	WT-042916-6550- B	< 1				
4 STEAD RECREATION CENTER	5/28/2016	WS- 006534	Fountain	Ground Floor	Exterior adjacent to back play ground Left Low	WT-042916-6551- A	< 1	WT-042916-6551- B	< 1				
5 STEAD RECREATION CENTER	5/28/2016	WS- 006535	Cooler	2	In hallway adjacent to restrooms	WT-042916-6552- A	< 1	WT-042916-6552- B	< 1				
6 STEAD RECREATION CENTER	5/28/2016	WS- 006536	Kitchen	2	In kitchen	WT-042916-6553- A	1.6	WT-042916-6553- B	< 1				
7 STEAD RECREATION CENTER	5/28/2016	WS- 006537	Cooler	1	In computer room	WT-042916-6554- A	< 1	WT-042916-6554- B	< 1				
8 STEAD RECREATION CENTER	5/28/2016	WS- 006538	Utility	1	In boiler room (water source)	WT-042916-6555- A	< 1	WT-042916-6555- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.