



Stuart Hobson Middle School Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 006907	4/18/2024	4/18/2025	1	Bottle Filler	In hallway adjacent to room 117	WF-04182024-006907	1/8/2025	FT-FY25-12042024-006907-A	<2	FT-FY25-12042024-006907-B	<2	
WS- 006940	8/30/2024	8/30/2025	2	Bottle Filler	In hallway adjacent to room 203	WF-08302024-006940	1/8/2025	FT-FY25-12042024-006940-A	<2	FT-FY25-12042024-006940-B	<2	
WS- 010596	4/18/2024	4/18/2025	Basement	Break Room	In break room G07D in library	WF-04182024-010596	1/8/2025	FT-FY25-12042024-010596-A	<2	FT-FY25-12042024-010596-B	<2	
WS- 010597	4/18/2024	4/18/2025	Basement	Cooler	In hallway adjacent to room G09	WF-04182024-010597	1/8/2025	FT-FY25-12042024-010597-A	<2	FT-FY25-12042024-010597-B	<2	
WS- 010598	4/18/2024	4/18/2025	Basement	Cooler	In hallway adjacent to room G05	WF-04182024-010598	1/8/2025	FT-FY25-12042024-010598-A	<2	FT-FY25-12042024-010598-B	<2	
WS- 010607	4/18/2024	4/18/2025	Basement	Cooler	In cafeteria on east wall	WF-04182024-010607	1/8/2025	FT-FY25-12042024-010607-A	<2	FT-FY25-12042024-010607-B	<2	
WS- 010614	4/18/2024	4/18/2025	1	Cooler	In hallway adjacent to room 105	WF-04182024-010614	1/8/2025	FT-FY25-12042024-010614-A	<2	FT-FY25-12042024-010614-B	<2	
WS- 010615	4/18/2024	4/18/2025	1	Combo Fountain	In health suite 104	Right	WF-04182024-010615	1/8/2025	FT-FY25-12042024-010615-A	<2	FT-FY25-12042024-010615-B	<2
WS- 010617	4/18/2024	4/18/2025	1	Break Room	In break room 105	WF-04182024-010617	1/8/2025	FT-FY25-12042024-010617-A	<2	FT-FY25-12042024-010617-B	<2	
WS- 010619	4/18/2024	4/18/2025	1	Cooler	In hallway adjacent to girls' restroom	WF-04182024-010619	1/8/2025	FT-FY25-12042024-010619-A	<2	FT-FY25-12042024-010619-B	<2	
WS- 010620	4/18/2024	4/18/2025	1	Cooler	In hallway adjacent to room 117	WF-04182024-010620	1/8/2025	FT-FY25-12042024-010620-A	<2	FT-FY25-12042024-010620-B	<2	
WS- 010628	4/18/2024	4/18/2025	1	Break Room	In break room 120	Left	WF-04182024-010628	1/8/2025	FT-FY25-12042024-010628-A	<2	FT-FY25-12042024-010628-B	<2
WS- 010636	4/18/2024	4/18/2025	2	Cooler	In hallway adjacent to room 218	WF-04182024-010636	1/8/2025	FT-FY25-12042024-010636-A	<2	FT-FY25-12042024-010636-B	<2	
WS- 010639	8/30/2024	8/30/2025	2	Cooler	In hallway adjacent to room 203	WF-08302024-010639	1/8/2025	FT-FY25-12042024-010639-A	<2	FT-FY25-12042024-010639-B	<2	
WS- 010640	9/11/2024	9/11/2025	2	Combo Faucet	In classroom 201	Left	WF-09112024-010640	1/8/2025	FT-FY25-12042024-010640-A	<2	FT-FY25-12042024-010640-B	<2
WS- 010641	4/18/2024	4/18/2025	2	Combo Fountain	In classroom 201	Right	WF-04182024-010641	1/8/2025	FT-FY25-12042024-010641-A	<2	FT-FY25-12042024-010641-B	<2
WS- 010648	4/18/2024	4/18/2025	3	Cooler	In hallway adjacent to room 304	WF-04182024-010648	1/8/2025	FT-FY25-12042024-010648-A	<2	FT-FY25-12042024-010648-B	<2	
WS- 010649	4/18/2024	4/18/2025	3	Cooler	In hallway adjacent to room 312	WF-04182024-010649	1/8/2025	FT-FY25-12042024-010649-A	<2	FT-FY25-12042024-010649-B	<2	
WS- 010650	4/18/2024	4/18/2025	3	Break Room	In break room 310	WF-04182024-010650	1/8/2025	FT-FY25-12042024-010650-A	<2	FT-FY25-12042024-010650-B	<2	

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 010609	12/30/2024	12/30/2025	Basement	Food Prep Sink	In kitchen second clockwise from entry door	Mid	WF-12302024-010609	1/8/2025	FT-FY25-12042024-010609-A	<2	FT-FY25-12042024-010609-B	<2
WS- 010611	12/30/2024	12/30/2025	Basement	Food Prep Sink	In kitchen fifth clockwise from entry door	WF-12302024-010611	1/8/2025	FT-FY25-12042024-010611-A	<2	FT-FY25-12042024-010611-B	<2	

FY25 Filter Test

Greater than 5ppb - Devices requiring remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 010616	4/18/2024	4/18/2025	1	Health Suite	In health suite 104	Left	WF-04182024-010616	1/8/2025	FT-FY25-12042024-010616-A	5.3	FT-FY25-12042024-010616-B	<2

After First Re-test (Plumbing Check)

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010616	1/10/2025	1/10/2026	1	Health Suite	In health suite 104	Left	WF-01102025-010616	1/28/2025	FT-FY25-01102025-010616-A	<2	FT-FY25-01102025-010616-B	<2