



Stuart Hobson Middle School Lead Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation													
RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-010592	6/7/2017	6/7/2018	Ground	Bottle Filler	In hallway adjacent to room L11 (bottle filler)	Left	High	WF-62017-010592	12/14/2017	FT-FY18--62017-010592-A	<1	FT-FY18--62017-010592-B	<1
WS-010594	6/7/2017	6/7/2018	Ground	Cooler	In hallway adjacent to room L11	Right		WF-62017-010594	12/14/2017	FT-FY18--62017-010594-A	<1	FT-FY18--62017-010594-B	<1
WS-010597	6/7/2017	6/7/2018	Basement	Cooler	In hallway adjacent to room G09			WF-62017-010597	12/14/2017	FT-FY18--62017-010597-A	<1	FT-FY18--62017-010597-B	<1
WS-010598	6/7/2017	6/7/2018	Basement	Cooler	In hallway adjacent to room G05			WF-62017-010598	12/14/2017	FT-FY18--62017-010598-A	<1	FT-FY18--62017-010598-B	<1
WS-010616	6/7/2017	6/7/2018	1	Health Suite	In health suite 104	Left		WF-62017-010616	12/14/2017	FT-FY18--62017-010616-A	<1	FT-FY18--62017-010616-B	<1
WS-010620	6/7/2017	6/7/2018	1	Cooler	In hallway adjacent to room 117			WF-62017-010620	12/14/2017	FT-FY18--62017-010620-A	<1	FT-FY18--62017-010620-B	<1
WS-010628	6/7/2017	6/7/2018	1	Break Room	In break room 120	Left		WF-62017-010628	12/14/2017	FT-FY18--62017-010628-A	<1	FT-FY18--62017-010628-B	<1
WS-010641	6/7/2017	6/7/2018	2	Combo Fountain	In classroom 201	Right		WF-62017-010641	12/14/2017	FT-FY18--62017-010641-A	<1	FT-FY18--62017-010641-B	<1
WS-010650	6/7/2017	6/7/2018	3	Break Room	In break room 310			WF-62017-010650	12/14/2017	FT-FY18--62017-010650-A	<1	FT-FY18--62017-010650-B	<1

Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation										
RECORD ID	Floor	Device Type	Device Location			Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-010609	Basement	Food Prep Sink	In kitchen second clockwise from entry door	Mid		12/14/2017	FT-FY18-102017-010609-A	<1	FT-FY18-102017-010609-B	<1
WS-010610	Basement	Food Prep Sink	In kitchen third clockwise from entry door	Right		12/14/2017	FT-FY18-102017-010610-A	<1	FT-FY18-102017-010610-B	<1