



Stuart-Hobson MS Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006907	4/8/2025	4/8/2026	1	Bottle Filler	In hallway adjacent to room 117	WF-04082025-006907	1/21/2026	FT-FY26-12302025-006907-A	<2	FT-FY26-12302025-006907-B	<2
WS- 006940	5/14/2025	5/14/2026	2	Bottle Filler	In hallway adjacent to room 203	WF-05142025-006940	1/21/2026	FT-FY26-12302025-006940-A	<2	FT-FY26-12302025-006940-B	<2
WS- 010596	4/8/2025	4/8/2026	Basement	Break Room	In break room G07D in library	WF-04082025-010596	1/21/2026	FT-FY26-12302025-010596-A	<2	FT-FY26-12302025-010596-B	<2
WS- 010597	4/8/2025	4/8/2026	Basement	Cooler	In hallway adjacent to room G09	WF-04082025-010597	1/21/2026	FT-FY26-12302025-010597-A	<2	FT-FY26-12302025-010597-B	<2
WS- 010598	4/8/2025	4/8/2026	Basement	Cooler	In hallway adjacent to room G05	WF-04082025-010598	1/21/2026	FT-FY26-12302025-010598-A	<2	FT-FY26-12302025-010598-B	<2
WS- 010604	4/8/2025	4/8/2026	Basement	Cooler	In hallway adjacent to room G15 High Left	WF-04082025-010604	1/21/2026	FT-FY26-12302025-010604-A	<2	FT-FY26-12302025-010604-B	<2
WS- 010605	4/8/2025	4/8/2026	Basement	Cooler	In hallway adjacent to room G15 Low Right	WF-04082025-010605	1/21/2026	FT-FY26-12302025-010605-A	<2	FT-FY26-12302025-010605-B	<2
WS- 010607	4/8/2025	4/8/2026	Basement	Cooler	In cafeteria on east wall	WF-04082025-010607	1/21/2026	FT-FY26-12302025-010607-A	<2	FT-FY26-12302025-010607-B	<2
WS- 010614	4/8/2025	4/8/2026	1	Cooler	In hallway adjacent to room 105	WF-04082025-010614	1/21/2026	FT-FY26-12302025-010614-A	<2	FT-FY26-12302025-010614-B	<2
WS- 010615	4/8/2025	4/8/2026	1	Combo Fountain	In health suite 104 Right	WF-04082025-010615	1/21/2026	FT-FY26-12302025-010615-A	<2	FT-FY26-12302025-010615-B	<2
WS- 010616	4/8/2025	4/8/2026	1	Health Suite	In health suite 104 Left	WF-04082025-010616	1/21/2026	FT-FY26-12302025-010616-A	2.7	FT-FY26-12302025-010616-B	<2
WS- 010617	4/8/2025	4/8/2026	1	Break Room	In break room 105	WF-04082025-010617	1/21/2026	FT-FY26-12302025-010617-A	<2	FT-FY26-12302025-010617-B	<2
WS- 010619	4/8/2025	4/8/2026	1	Cooler	In hallway adjacent to girls' restroom	WF-04082025-010619	1/21/2026	FT-FY26-12302025-010619-A	<2	FT-FY26-12302025-010619-B	<2
WS- 010620	4/8/2025	4/8/2026	1	Cooler	In hallway adjacent to room 117	WF-04082025-010620	1/21/2026	FT-FY26-12302025-010620-A	<2	FT-FY26-12302025-010620-B	<2
WS- 010628	4/8/2025	4/8/2026	1	Break Room	In break room 120 Left	WF-04082025-010628	1/21/2026	FT-FY26-12302025-010628-A	<2	FT-FY26-12302025-010628-B	<2
WS- 010636	4/8/2025	4/8/2026	2	Cooler	In hallway adjacent to room 218	WF-04082025-010636	1/21/2026	FT-FY26-12302025-010636-A	<2	FT-FY26-12302025-010636-B	<2
WS- 010638	4/8/2025	4/8/2026	2	Cooler	In hallway adjacent to room 213	WF-04082025-010638	1/21/2026	FT-FY26-12302025-010638-A	<2	FT-FY26-12302025-010638-B	<2
WS- 010639	5/14/2025	5/14/2026	2	Cooler	In hallway adjacent to room 203	WF-05142025-010639	1/21/2026	FT-FY26-12302025-010639-A	<2	FT-FY26-12302025-010639-B	<2
WS- 010640	9/4/2025	9/4/2026	2	Combo Faucet	In classroom 201 Left	WF-09042025-010640	1/21/2026	FT-FY26-12302025-010640-A	3.9	FT-FY26-12302025-010640-B	<2
WS- 010641	4/8/2025	4/8/2026	2	Combo Fountain	In classroom 201 Right	WF-04082025-010641	1/21/2026	FT-FY26-12302025-010641-A	<2	FT-FY26-12302025-010641-B	<2
WS- 010648	4/8/2025	4/8/2026	3	Cooler	In hallway adjacent to room 304	WF-04082025-010648	1/21/2026	FT-FY26-12302025-010648-A	<2	FT-FY26-12302025-010648-B	<2
WS- 010649	4/8/2025	4/8/2026	3	Cooler	In hallway adjacent to room 312	WF-04082025-010649	1/21/2026	FT-FY26-12302025-010649-A	<2	FT-FY26-12302025-010649-B	<2
WS- 010650	4/8/2025	4/8/2026	3	Break Room	In break room 310	WF-04082025-010650	1/21/2026	FT-FY26-12302025-010650-A	<2	FT-FY26-12302025-010650-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010609	12/3/2025	12/3/2026	Basement	Food Prep Sink	In kitchen second clockwise from entry door Mid	WF-12032025-010609	1/21/2026	FT-FY26-12302025-010609-A	<2	FT-FY26-12302025-010609-B	<2
WS- 010611	12/3/2025	12/3/2026	Basement	Food Prep Sink	In kitchen fifth clockwise from entry door	WF-12032025-010611	1/21/2026	FT-FY26-12302025-010611-A	<2	FT-FY26-12302025-010611-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.