



# Trinidad RC Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011874	9/27/2018	9/27/2019	1	Cooler	In hallway adjacent to reception desk	High Left	WF-09272018-011874	2/25/2019	FT-FY19-022019-011874-A	<1	FT-FY19-022019-011874-B	<1
WS- 011875	9/27/2018	9/27/2019	1	Cooler	In hallway adjacent to reception desk	Low Right	WF-09272018-011875	2/25/2019	FT-FY19-022019-011875-A	<1	FT-FY19-022019-011875-B	<1
WS- 011876	9/27/2018	9/27/2019	1	Cooler	In hallway across from gym 100	Low Right	WF-09272018-011876	2/25/2019	FT-FY19-022019-011876-A	<1	FT-FY19-022019-011876-B	<1
WS- 011877	9/27/2018	9/27/2019	1	Cooler	In hallway across from gym 100	High Left	WF-09272018-011877	2/25/2019	FT-FY19-022019-011877-A	<1	FT-FY19-022019-011877-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011878	5/1/2018	5/1/2019	1	Food Prep Sink	In pantry room 125		WF-05012018-011878	2/25/2019	FT-FY19-022019-011878-A	<1	FT-FY19-022019-011878-B	<1