



Trinidad RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011874	4/11/2019	4/11/2020	1	Cooler	In hallway adjacent to reception desk	High Left	WF-04112019-011874	2/26/2020	FT-FY20-012020-011874-A	<1	FT-FY20-012020-011874-B	<1
WS- 011875	4/11/2019	4/11/2020	1	Cooler	In hallway adjacent to reception desk	Low Right	WF-04112019-011875	2/26/2020	FT-FY20-012020-011875-A	<1	FT-FY20-012020-011875-B	<1
WS- 011876	10/30/2019	10/30/2020	1	Cooler	In hallway across from gym 100	Low Right	WF-10302019-011876	2/26/2020	FT-FY20-012020-011876-A	<1	FT-FY20-012020-011876-B	<1
WS- 011877	10/30/2019	10/30/2020	1	Cooler	In hallway across from gym 100	High Left	WF-10302019-011877	2/26/2020	FT-FY20-012020-011877-A	<1	FT-FY20-012020-011877-B	<1
WS- 011878	4/11/2019	4/11/2020	1	Food Prep Sink	In pantry room 125		WF-04112019-011878	2/26/2020	FT-FY20-012020-011878-A	<1	FT-FY20-012020-011878-B	<1