



# Trinidad RC Lead in Water Test Results

## FY21 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011874	3/24/2021	3/24/2022	1	Cooler	In hallway adjacent to reception desk	High	Left	WF-03242021-011874	5/7/2021	FT-FY21-042021-011874-A	<1	FT-FY21-042021-011874-B	<1
WS- 011875	3/24/2021	3/24/2022	1	Cooler	In hallway adjacent to reception desk	Low	Right	WF-03242021-011875	5/7/2021	FT-FY21-042021-011875-A	<1	FT-FY21-042021-011875-B	<1
WS- 011876	3/24/2021	3/24/2022	1	Cooler	In hallway across from gym 100	Low	Right	WF-03242021-011876	5/7/2021	FT-FY21-042021-011876-A	<1	FT-FY21-042021-011876-B	<1
WS- 011877	3/24/2021	3/24/2022	1	Cooler	In hallway across from gym 100	High	Left	WF-03242021-011877	5/7/2021	FT-FY21-042021-011877-A	<1	FT-FY21-042021-011877-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011878	1/28/2021	1/28/2022	1	Food Prep Sink	In pantry room 125			WF-01282021-011878	5/7/2021	FT-FY21-042021-011878-A	<1	FT-FY21-042021-011878-B	<1