



# TRINIDAD REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 TRINIDAD REC CTR	5/19/2016	WS-011873	Utility	1	In room 113 janitor (water source)	WT-042916-11890-A	< 2	WT-042916-11890-B	< 2				
2 TRINIDAD REC CTR	5/19/2016	WS-011874	Cooler	1	In hallway adjacent to reception desk Left High	WT-042916-11891-A	< 2	WT-042916-11891-B	< 2				
3 TRINIDAD REC CTR	5/19/2016	WS-011875	Cooler	1	In hallway adjacent to reception desk Right Low	WT-042916-11892-A	< 2	WT-042916-11892-B	< 2				
4 TRINIDAD REC CTR	5/19/2016	WS-011876	Cooler	1	In hallway across from gymnasium 100 Right Low	WT-042916-11893-A	< 2	WT-042916-11893-B	< 2				
5 TRINIDAD REC CTR	5/19/2016	WS-011877	Cooler	1	In hallway across from gymnasium 100 Left High	WT-042916-11894-A	< 2	WT-042916-11894-B	< 2				
6 TRINIDAD REC CTR	5/19/2016	WS-011878	Kitchen	1	In room 125 pantry	WT-042916-11895-A	< 2	WT-042916-11895-B	< 2				
7 TRINIDAD REC CTR	5/12/2016	WS-011879	Fountain	1	Exterior, adjacent to playground Right High	WT-042916-11896-A	< 2	WT-042916-11896-B	< 2				
8 TRINIDAD REC CTR	5/19/2016	WS-011880	Fountain	1	Exterior adjacent to playground Left Low	WT-042916-11897-A	< 2	WT-042916-11897-B	< 2				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.