



# TRUEDELL LEAD WATER TEST RESULTS

May 11th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest Results
1	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 000999	Utility	Basement	Annex main water line in room 015 (water source)	WT-042916-1016- A	< 1	WT-042916-1016- B	< 1			
2	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001000	Cooler	Basement	Annex in hallway, adjacent to room 013	WT-042916-1017- A	< 1	WT-042916-1017- B	< 1			
3	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001001	Health Suite	Basement	Annex in health suite 011	WT-042916-1018- A	< 1	WT-042916-1018- B	< 1			
4	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001002	Fountain	Basement	Annex in health suite 011	WT-042916-1019- A	< 1	WT-042916-1019- B	< 1			
5	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001003	Cooler	1	Annex in hallway adjacent to room 130	WT-042916-1020- A	< 1	WT-042916-1020- B	< 1			
6	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001004	Cooler	1	Annex, in hallway adjacent to room 117	WT-042916-1021- A	< 1	WT-042916-1021- B	< 1			
7	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001005	Cooler	2	Annex in hallway adjacent to room 218	WT-042916-1022- A	< 1	WT-042916-1022- B	< 1			
8	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001006	Cooler	2	Annex in hallway adjacent to staff restroom 226	WT-042916-1023- A	< 1	WT-042916-1023- B	< 1			
9	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001007	Utility	Basement	Boiler room (second water source)	WT-042916-1024- A	2.16	WT-042916-1024- B	3.96			
10	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001008	Cooler	1	In hallway adjacent to operations office	WT-042916-1025- A	< 1	WT-042916-1025- B	< 1			
11	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001009	Cooler	1	In hallway adjacent to corridor 104	WT-042916-1026- A	< 1	WT-042916-1026- B	< 1			
12	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001010	Classroom	1	In room 100 Left	WT-042916-1027- A	< 1	WT-042916-1027- B	< 1			
13	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001011	Fountain	1	In room 100 Right	WT-042916-1028- A	< 1	WT-042916-1028- B	< 1			
14	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001012	Fountain	1	In room 101 Right	WT-042916-1029- A	< 1	WT-042916-1029- B	< 1			
15	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001013	Classroom	1	In room 101 Left	WT-042916-1030- A	< 1	WT-042916-1030- B	< 1			
16	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001014	Cooler	2	In hallway adjacent to room 200	WT-042916-1031- A	< 1	WT-042916-1031- B	< 1			
17	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001015	Cooler	2	In hallway adjacent to room 212	WT-042916-1032- A	< 1	WT-042916-1032- B	< 1			
18	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001016	Classroom	2	In room 200 Left	WT-042916-1033- A	6.33	WT-042916-1033- B	1.27			
19	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001017	Fountain	2	In room 200 Right	WT-042916-1034- A	1.02	WT-042916-1034- B	< 1			
20	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001018	Fountain	2	In room 201 Right	WT-042916-1035- A	< 1	WT-042916-1035- B	< 1			
21	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001019	Classroom	2	In room 201 Left	WT-042916-1036- A	< 1	WT-042916-1036- B	< 1			
22	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001020	Fountain	2	In room 217 Right	WT-042916-1037- A	< 1	WT-042916-1037- B	< 1			
23	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001021	Classroom	2	In room 217 Left	WT-042916-1038- A	< 1	WT-042916-1038- B	< 1			
24	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001022	Fountain	2	In room 216 Right	WT-042916-1039- A	< 1	WT-042916-1039- B	< 1			
25	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001023	Classroom	2	In room 216 Left	WT-042916-1040- A	< 1	WT-042916-1040- B	< 1			
26	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001024	Cooler	3	In hallway adjacent to room 308	WT-042916-1041- A	< 1	WT-042916-1041- B	< 1			



# TRUEDELL LEAD WATER TEST RESULTS

May 11th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest Results
27	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001025	Cooler	3	In hallway adjacent to room 300	WT-042916-1042- A	< 1	WT-042916-1042- B	< 1			
28	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001026	Kitchen	1	In kitchen room 110 Left	WT-042916-1043- A	< 1	WT-042916-1043- B	< 1			
29	TRUEDELL EDUCATIONAL CAMPUS	5/3/2016	WS- 001027	Kitchen	1	In kitchen room 110 Right	WT-042916-1044- A	< 1	WT-042916-1044- B	< 1			

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.