UDC Van Ness Swing Space Lead Water Test Results

FY20 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	**Filter Installed Date**	**Filter Expiration Date**	**Floor**	**Device Type**	**Device Location**	**Water Filter's Name**	**Date Analyzed**	**1st Draw - Sample ID**	**FT Final Result - 1st Draw (ppb)**	**2nd Draw - Sample ID**	**FT Final Result - 2nd Draw (ppb)**
WS- 003200	8/1/2019	8/1/2020	Ground Floor	Health Suite	In health suite in A wing	WF-08012019-003200	8/13/2019	FT-FY20-082019-003200-A	<1	FT-FY20-082019-003200-B	<1
WS- 003201	8/1/2019	8/1/2020	Ground Floor	Cooler	In lobby adjacent to D wing restrooms High Left	WF-08012019-003201	8/13/2019	FT-FY20-082019-003201-A	<1	FT-FY20-082019-003201-B	<1
WS- 003202	8/1/2019	8/1/2020	Ground Floor	Cooler	In lobby adjacent to D wing restrooms Low Left	WF-08012019-003202	8/13/2019	FT-FY20-082019-003202-A	<1	FT-FY20-082019-003202-B	<1
WS- 003203	8/1/2019	8/1/2020	Ground Floor	Cooler	In lobby adjacent to D wing restrooms High Right	WF-08012019-003203	8/13/2019	FT-FY20-082019-003203-A	<1	FT-FY20-082019-003203-B	<1
WS- 003204	8/1/2019	8/1/2020	Ground Floor	Cooler	In lobby adjacent to D wing restrooms Low Right	WF-08012019-003204	8/13/2019	FT-FY20-082019-003204-A	<1	FT-FY20-082019-003204-B	<1
WS- 003205	8/1/2019	8/1/2020	Ground Floor	Cooler	In lobby adjacent to C wing restrooms High Left	WF-08012019-003205	8/13/2019	FT-FY20-082019-003205-A	<1	FT-FY20-082019-003205-B	<1
WS- 003206	8/1/2019	8/1/2020	Ground Floor	Cooler	In lobby adjacent to C wing restrooms Low Left	WF-08012019-003206	8/13/2019	FT-FY20-082019-003206-A	<1	FT-FY20-082019-003206-B	<1
WS- 003207	8/1/2019	8/1/2020	Ground Floor	Cooler	In lobby adjacent to C wing restrooms High Right	WF-08012019-003207	8/13/2019	FT-FY20-082019-003207-A	<1	FT-FY20-082019-003207-B	<1
WS- 003208	8/1/2019	8/1/2020	Ground Floor	Cooler	In lobby adjacent to C wing restrooms Low Right	WF-08012019-003208	8/13/2019	FT-FY20-082019-003208-A	<1	FT-FY20-082019-003208-B	<1
WS- 003230	8/1/2019	8/1/2020	Ground Floor	Classroom Faucet	In room D105	WF-08012019-003230	8/13/2019	FT-FY20-082019-003230-A	<1	FT-FY20-082019-003230-B	<1
WS- 003231	8/1/2019	8/1/2020	Ground Floor	Classroom Faucet	In room D101	WF-08012019-003231	8/13/2019	FT-FY20-082019-003231-A	2.3	FT-FY20-082019-003231-B	<1
WS- 003232	8/1/2019	8/1/2020	Ground Floor	Classroom Faucet	In room D108	WF-08012019-003232	8/13/2019	FT-FY20-082019-003232-A	1.8	FT-FY20-082019-003232-B	<1
WS- 003233	8/1/2019	8/1/2020	Ground Floor	Classroom Faucet	In room D100	WF-08012019-003233	8/13/2019	FT-FY20-082019-003233-A	1.2	FT-FY20-082019-003233-B	<1
WS- 003234	8/1/2019	8/1/2020	Ground Floor	Classroom Faucet	In room D107	WF-08012019-003234	8/13/2019	FT-FY20-082019-003234-A	1.5	FT-FY20-082019-003234-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	**Filter Installed Date**	**Filter Expiration Date**	**Floor**	**Device Type**	**Device Location**	**Water Filter's Name**	**Date Analyzed**	**1st Draw - Sample ID**	**FT Final Result - 1st Draw (ppb)**	**2nd Draw - Sample ID**	**FT Final Result - 2nd Draw (ppb)**
WS- 003235	8/1/2019	8/1/2020	Ground Floor	Food Prep Sink	In kitchen Right	WF-08012019-003235	8/13/2019	FT-FY20-082019-003235-A	3.2	FT-FY20-082019-003235-B	<1