



UPSHUR REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 UPSHUR	5/20/2016	WS- 005016	Fountain	Ground Floor	Exterior adjacent to pool building women's locker room	WT-042916-5033- A	< 1	WT-042916-5033- B	< 1				
2 UPSHUR	5/20/2016	WS- 005021	Fountain	Ground Floor	Exterior in middle of two pools	WT-042916-5038- A	< 1	WT-042916-5038- B	< 1				
3 UPSHUR	5/20/2016	WS- 005024	Fountain	Ground Floor	Exterior adjacent to basketball court Right High	WT-042916-5041- A	< 1	WT-042916-5041- B	< 1				
4 UPSHUR	5/20/2016	WS- 005025	Fountain	Ground Floor	Exterior adjacent to basketball court Left Low	WT-042916-5042- A	< 1	WT-042916-5042- B	< 1				
5 UPSHUR	5/20/2016	WS- 005026	Cooler	1	In lobby adjacent to closet	WT-042916-5043- A	< 1	WT-042916-5043- B	< 1				
6 UPSHUR	5/20/2016	WS- 005027	Kitchen	1	In kitchen	WT-042916-5044- A	< 1	WT-042916-5044- B	< 1				
7 UPSHUR	5/20/2016	WS- 005780	Utility	Ground Floor	In filtration room in pool building (water source)	WT-042916-5797- A	7.3	WT-042916-5797- B	4.8				
8 UPSHUR	5/20/2016	WS- 011881	Fountain	Ground Floor	Exterior adjacent to kids pool	WT-042916-11898- A	11.7	WT-042916-11898- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.