



# VAN NESS LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location		1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	VAN NESS	WS- 003827	8/23/2016	3	Cooler	In hallway across from stairwell B	High Left	FT-82016-003827-A	< 1	FT-82016-003827-B	< 1
2	VAN NESS	WS- 003828	8/23/2016	3	Cooler	In hallway across from stairwell B	Low Right	FT-82016-003828-A	< 1	FT-82016-003828-B	< 1
3	VAN NESS	WS- 003829	8/23/2016	3	Bottle Filler	In hallway across from stairwell B (bottle filler)		FT-82016-003829-A	< 1	FT-82016-003829-B	< 1
4	VAN NESS	WS- 003830	8/23/2016	3	Fountain	In classroom 302	Left	FT-82016-003830-A	< 1	FT-82016-003830-B	< 1
5	VAN NESS	WS- 003831	8/23/2016	3	Fountain	In classroom 306	Right	FT-82016-003831-A	< 1	FT-82016-003831-B	< 1
6	VAN NESS	WS- 003832	8/23/2016	3	Fountain	In classroom 307	Right	FT-82016-003832-A	< 1	FT-82016-003832-B	< 1
7	VAN NESS	WS- 003833	8/23/2016	3	Fountain	In classroom 311	Left	FT-82016-003833-A	< 1	FT-82016-003833-B	< 1
8	VAN NESS	WS- 003834	8/23/2016	3	Fountain	In classroom 308	Left	FT-82016-003834-A	< 1	FT-82016-003834-B	< 1
9	VAN NESS	WS- 003835	8/23/2016	3	Fountain	In classroom 312	Right	FT-82016-003835-A	< 1	FT-82016-003835-B	< 1
10	VAN NESS	WS- 003836	8/23/2016	Ground Floor	Cooler	In hallway adjacent to cafeteria	High Left	FT-82016-003836-A	< 1	FT-82016-003836-B	< 1
11	VAN NESS	WS- 003837	8/23/2016	Ground Floor	Cooler	In hallway adjacent to cafeteria	Low Right	FT-82016-003837-A	< 1	FT-82016-003837-B	< 1
12	VAN NESS	WS- 003838	8/23/2016	1	Bottle Filler	In hallway adjacent to cafeteria (bottle filler)		FT-82016-003838-A	< 1	FT-82016-003838-B	< 1
13	VAN NESS	WS- 010339	8/23/2016	1	Cooler	In hallway adjacent to room 136	High Left	FT-82016-010339-A	< 1	FT-82016-010339-B	< 1
14	VAN NESS	WS- 010340	8/23/2016	1	Cooler	In hallway adjacent to room 136	Low Right	FT-82016-010340-A	< 1	FT-82016-010340-B	< 1
15	VAN NESS	WS- 010341	8/23/2016	1	Bottle Filler	In hallway adjacent to room 136 (bottle filler)	High Right	FT-82016-010341-A	< 1	FT-82016-010341-B	1.6
16	VAN NESS	WS- 010342	8/23/2016	1	Fountain	In classroom 136	Low Left	FT-82016-010342-A	< 1	FT-82016-010342-B	< 1
17	VAN NESS	WS- 010344	8/23/2016	1	Fountain	In classroom 134	Low Right	FT-82016-010344-A	< 1	FT-82016-010344-B	< 1
18	VAN NESS	WS- 010346	8/23/2016	1	Fountain	In classroom 132	Low Left	FT-82016-010346-A	< 1	FT-82016-010346-B	< 1
19	VAN NESS	WS- 010349	8/23/2016	1	Fountain	In classroom 130	Low Right	FT-82016-010349-A	< 1	FT-82016-010349-B	< 1
20	VAN NESS	WS- 010352	8/23/2016	2	Fountain	In classroom 219	Low Right	FT-82016-010352-A	< 1	FT-82016-010352-B	< 1
21	VAN NESS	WS- 010355	8/23/2016	2	Fountain	In classroom 210	Left	FT-82016-010355-A	< 1	FT-82016-010355-B	< 1
22	VAN NESS	WS- 010358	8/23/2016	2	Cooler	In hallway adjacent to stairwell B	High Left	FT-82016-010358-A	< 1	FT-82016-010358-B	< 1
23	VAN NESS	WS- 010359	8/23/2016	2	Bottle Filler	In hallway adjacent to stairwell B (bottle filler)	Low Right	FT-82016-010359-A	< 1	FT-82016-010359-B	< 1
24	VAN NESS	WS- 010362	8/23/2016	2	Fountain	In classroom 217	Left	FT-82016-010362-A	< 1	FT-82016-010362-B	< 1
25	VAN NESS	WS- 010363	8/23/2016	2	Cooler	In hallway adjacent to stairwell B	Low Right	FT-82016-010363-A	< 1	FT-82016-010363-B	< 1
26	VAN NESS	WS- 010368	8/23/2016	1	Food Prep Sink	In kitchen		FT-82016-010368-A	< 1	FT-82016-010368-B	< 1
27	VAN NESS	WS- 010369	8/23/2016	1	Health Suite	In treatment room 126A in health suite		FT-82016-010369-A	< 1	FT-82016-010369-B	< 1