



Volta Park RC Lead in Water Test Results

FY21 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012009	6/5/2020	6/5/2021	1	Cooler	In hallway adjacent to office Low Right	WF-06052020-012009	3/25/2021	FT-FY21-032021-012009-A	<1	FT-FY21-032021-012009-B	<1
WS- 012014	6/5/2020	6/5/2021	1	Cooler	In hallway adjacent to office High Left	WF-06052020-012014	3/25/2021	FT-FY21-032021-012014-A	<1	FT-FY21-032021-012014-B	<1
WS- 012036	6/5/2020	6/5/2021	1	Bottle Filler	In hallway adjacent to office	WF-06052020-012036	3/25/2021	FT-FY21-032021-012036-A	<1	FT-FY21-032021-012036-B	<1