



Volta Park RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012009	7/12/2018	7/12/2019	1	Cooler	In hallway adjacent to office Low Right	WF-07122018-012009	1/25/2019	FT-FY19-012019-012009-A	<1	FT-FY19-012019-012009-B	<1
WS- 012014	7/12/2018	7/12/2019	1	Cooler	In hallway adjacent to office High Left	WF-07122018-012014	1/25/2019	FT-FY19-012019-012014-A	<1	FT-FY19-012019-012014-B	<1
WS- 012036	7/11/2018	7/11/2019	1	Bottle Filler	In hallway adjacent to office	WF-07112018-012036	1/25/2019	FT-FY19-012019-012036-A	<1	FT-FY19-012019-012036-B	<1