



WASHINGTON METRO LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 Washington Metropolitan HS	5/18/2016	WS- 011962	Utility	Basement	In boiler room	WT-042916-11979- A	1.3	WT-042916-11979- B	< 1				
2 Washington Metropolitan HS	5/18/2016	WS- 011963	Classroom	1	In classroom 106 Left	WT-042916-11980- A	860	WT-042916-11980- B	2.8	Filter will be installed and then retested			
3 Washington Metropolitan HS	5/18/2016	WS- 011964	Classroom	1	In classroom 106 Right	WT-042916-11981- A	35	WT-042916-11981- B	3.9	Filter will be installed and then retested			
4 Washington Metropolitan HS	5/18/2016	WS- 011965	Classroom	1	In classroom 103 Left	WT-042916-11982- A	47	WT-042916-11982- B	9.2	Filter will be installed and then retested			
5 Washington Metropolitan HS	5/18/2016	WS- 011966	Classroom	1	In classroom 103 Right	WT-042916-11983- A	150	WT-042916-11983- B	10	Filter will be installed and then retested			
6 Washington Metropolitan HS	5/18/2016	WS- 011967	Cooler	1	In hallway adjacent to men's restroom	WT-042916-11984- A	< 1	WT-042916-11984- B	< 1				
7 Washington Metropolitan HS	5/18/2016	WS- 011968	Cooler	1	In hallway adjacent to classroom 106	WT-042916-11985- A	< 1	WT-042916-11985- B	< 1				
8 Washington Metropolitan HS	5/18/2016	WS- 011969	Other	1	In kitchen (ice maker)	WT-042916-11986- A	1.4	WT-042916-11986- B	1.7				
9 Washington Metropolitan HS	5/18/2016	WS- 011970	Kitchen	1	In kitchen Left	WT-042916-11987- A	< 1	WT-042916-11987- B	< 1				
10 Washington Metropolitan HS	5/18/2016	WS- 011971	Other	1	In kitchen (spray nozzle)	WT-042916-11988- A	1.3	WT-042916-11988- B	< 1				
11 Washington Metropolitan HS	5/18/2016	WS- 011972	Kitchen	1	In kitchen Right	WT-042916-11989- A	< 1	WT-042916-11989- B	< 1				
12 Washington Metropolitan HS	5/18/2016	WS- 011973	Cooler	2	In hallway adjacent to men's restroom	WT-042916-11990- A	< 1	WT-042916-11990- B	< 1				
13 Washington Metropolitan HS	5/18/2016	WS- 011974	Cooler	2	In hallway adjacent to room 210	WT-042916-11991- A	< 1	WT-042916-11991- B	< 1				
14 Washington Metropolitan HS	5/18/2016	WS- 011975	Cooler	3	In hallway adjacent to room 312	WT-042916-11992- A	< 1	WT-042916-11992- B	< 1				
15 Washington Metropolitan HS	5/18/2016	WS- 011976	Cooler	3	In hallway adjacent to room 303	WT-042916-11993- A	< 1	WT-042916-11993- B	< 1				
16 Washington Metropolitan HS	5/18/2016	WS- 011977	Classroom	3	In classroom 302 Right	WT-042916-11994- A	3.6	WT-042916-11994- B	3				
17 Washington Metropolitan HS	5/18/2016	WS- 011978	Classroom	3	In classroom 302 Left	WT-042916-11995- A	< 1	WT-042916-11995- B	3.1				
18 Washington Metropolitan HS	5/18/2016	WS- 011979	Other	1	In nurses office (ice maker)	WT-042916-11996- A	< 1	WT-042916-11996- B	< 1				
19 Washington Metropolitan HS	5/18/2016	WS- 011980	Fountain	1	In nurses office	WT-042916-11997- A	31	WT-042916-11997- B	8.6	Filter will be installed and then retested			
20 Washington Metropolitan HS	5/18/2016	WS- 011981	Health Suite	1	In nurses office	WT-042916-11998- A	< 1	WT-042916-11998- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.