



# Wilson AC Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012031	4/9/2018	4/9/2019	1	Cooler	In hallway adjacent to room 113	High Left	WF-04092018-012031	2/11/2019	FT-FY19-022019-012031-A	<1	FT-FY19-022019-012031-B	<1
WS- 012032	4/9/2018	4/9/2019	1	Cooler	In hallway adjacent to room 114	Low Right	WF-04092018-012032	2/11/2019	FT-FY19-022019-012032-A	<1	FT-FY19-022019-012032-B	<1
WS- 012033	4/9/2018	4/9/2019	1	Cooler	In pool area	High Left	WF-04092018-012033	2/11/2019	FT-FY19-022019-012033-A	<1	FT-FY19-022019-012033-B	<1
WS- 012034	4/9/2018	4/9/2019	1	Cooler	In pool area	Low Right	WF-04092018-012034	2/11/2019	FT-FY19-022019-012034-A	<1	FT-FY19-022019-012034-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012029	4/9/2018	4/9/2019	2	Food Prep Sink	In recreation room 212		WF-04092018-012029	2/11/2019	FT-FY19-022019-012029-A	<1	FT-FY19-022019-012029-B	<1