



Wilson AC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 012029	3/20/2019	3/20/2020	2	Food Prep Sink	In recreation room 212	WF-03202019-012029	2/12/2020	FT-FY20-012020-012029-A	<1	FT-FY20-012020-012029-B	<1	
WS- 012031	3/20/2019	3/20/2020	1	Cooler	In hallway adjacent to room 113	High Left	WF-03202019-012031	2/12/2020	FT-FY20-012020-012031-A	<1	FT-FY20-012020-012031-B	<1
WS- 012032	3/20/2019	3/20/2020	1	Cooler	In hallway adjacent to room 114	Low Right	WF-03202019-012032	2/12/2020	FT-FY20-012020-012032-A	<1	FT-FY20-012020-012032-B	<1
WS- 012033	3/20/2019	3/20/2020	1	Cooler	In pool area	High Left	WF-03202019-012033	2/12/2020	FT-FY20-012020-012033-A	<1	FT-FY20-012020-012033-B	<1
WS- 012034	3/20/2019	3/20/2020	1	Cooler	In pool area	Low Right	WF-03202019-012034	2/12/2020	FT-FY20-012020-012034-A	<1	FT-FY20-012020-012034-B	<1
WS- 012382	3/20/2019	3/20/2020	2	Cooler	In hallway across from 219 spectator seating	High Left	WF-03202019-012382	2/12/2020	FT-FY20-012020-012382-A	<1	FT-FY20-012020-012382-B	<1
WS- 012383	3/20/2019	3/20/2020	2	Cooler	In hallway across from 219 spectator seating	Low Right	WF-03202019-012383	2/12/2020	FT-FY20-012020-012383-A	<1	FT-FY20-012020-012383-B	<1