



WILSON AQUATIC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	WILSON AQUATIC CENTER	5/28/2016	WS-012029	Kitchen	2	In recreation room 212	WT-042916-12046- A	< 1	WT-042916-12046- B	< 1				
2	WILSON AQUATIC CENTER	5/28/2016	WS-012030	Utility	Basement	In pump room (closest tap to main source)	WT-042916-12047- A	1.9	WT-042916-12047- B	< 1				
3	WILSON AQUATIC CENTER	5/28/2016	WS-012031	Cooler	1	In hallway adjacent to janitor room 113	WT-042916-12048- A	< 1	WT-042916-12048- B	< 1				
4	WILSON AQUATIC CENTER	5/28/2016	WS-012032	Cooler	1	In hallway adjacent to janitor room 113	WT-042916-12049- A	< 1	WT-042916-12049- B	< 1				
5	WILSON AQUATIC CENTER	5/28/2016	WS-012033	Cooler	1	Adjacent to main pool	WT-042916-12050- A	< 1	WT-042916-12050- B	< 1				
6	WILSON AQUATIC CENTER	5/28/2016	WS-012034	Cooler	1	Adjacent to main pool	WT-042916-12051- A	< 1	WT-042916-12051- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.