



# Wilson Aquatic Center Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012031	4/9/2018	4/9/2019	1	Cooler	In hallway adjacent to room 113	High	Left	WF-04092018-012031	2/11/2019	FT-FY19-022019-012031-A	<1	FT-FY19-022019-012031-B	<1
WS- 012032	4/9/2018	4/9/2019	1	Cooler	In hallway adjacent to room 114	Low	Right	WF-04092018-012032	2/11/2019	FT-FY19-022019-012032-A	<1	FT-FY19-022019-012032-B	<1
WS- 012033	4/9/2018	4/9/2019	1	Cooler	In pool area	High	Left	WF-04092018-012033	2/11/2019	FT-FY19-022019-012033-A	<1	FT-FY19-022019-012033-B	<1
WS- 012034	4/9/2018	4/9/2019	1	Cooler	In pool area	Low	Right	WF-04092018-012034	2/11/2019	FT-FY19-022019-012034-A	<1	FT-FY19-022019-012034-B	<1
WS- 012382	3/20/2019	3/20/2020	2	Cooler	In hallway across from 219 spectator seating	High	Left	WF-03202019-012382	5/24/2019	FT-FY19-052019-012382-A	<1	FT-FY19-052019-012382-B	<1
WS- 012383	3/20/2019	3/20/2020	2	Cooler	In hallway across from 219 spectator seating	Low	Right	WF-03202019-012383	5/24/2019	FT-FY19-052019-012383-A	<1	FT-FY19-052019-012383-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Floor	Device Type	Device Location					Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012029	2	Food Prep Sink	In recreation room 212					2/11/2019	FT-FY19-022019-012029-A	<1	FT-FY19-022019-012029-B	<1